





By appointment to
Her Majesty The Queen
Building Façade Restoration
and Conservation



Holy Trinity Maidstone

Long neglected skills had to be resurrected by our stonemasons to repair the famous Maidstone Landmark, Holy Trinity Church. Our masons had to use 19th Century stone cutting techniques to replace weather damaged Kentish ragstone in the 1827 Grade II listed building.

Redundant since 1974, the church had been seriously damaged by arson, fallen into disrepair, and had been heavily vandalised. The more exposed areas of the church such as quoins, cills, capitals and string courses suffered from weather damage and had to be replaced with newly carved stone. Kentish ragstone was a popular church building material in the 19th century but because it is very hard and variable, it is difficult to work.

The high level of craftsmanship required to work the difficult stone successfully means that we are one of only a few companies remaining who can undertake such a specialist type of work.

- **Cleaning**
- **Repair**
- **Conservation**
- **Extension**
- **Adaption**
- **Surveys**
- **Budgets**
- **Technical advice**



PAYE

www.payestone.co.uk

Stationmasters House Mottingham Station Approach London SE9 4EL
Telephone 020 8857 9111 Fax 020 8857 9222
enquiries@payestone.co.uk