



By appointment to
Her Majesty The Queen
Building Façade Restoration
and Conservation



Albert Memorial

The statue of Queen Victoria's husband Prince Albert had not been seen for eight years, since a large piece of lead cornice fell off and the monument was declared unsafe.

The restoration of the memorial took four years to complete and PAYE Stonework are proud to have been appointed as the specialised masonry contractor.

Our work involved the repair, realignment and rebuilding of the stone steps, paved areas and plinths.

Extensive research was required to match the original stone used and a combination of slate, sandstone, limestone, granite and marble was needed to restore the memorial back to its former glory.

- **Cleaning**
- **Repair**
- **Conservation**
- **Extension**
- **Adaption**
- **Surveys**
- **Budgets**
- **Technical advice**



PAYE

www.payestone.co.uk

Stationmasters House **Mottingham Station Approach London SE9 4EL**
Telephone 020 8857 9111 Fax 020 8857 9222
enquiries@payestone.co.uk