



By appointment to
Her Majesty The Queen
Building Façade Restoration
and Conservation




Maiden Lane Canal Bridge

As part of a project to reconstruct the Victorian Maiden Lane bridge over the Grand Union Canal in London experts from PAYE Stonework and Restoration rescued quoins, the bridge corner stones which have been scored with rope marks by the original barge traffic. These silent witnesses to a slower form of commercial transport were reused in the strengthened bridge.

The bridge was widened with new decking on a prefabricated steel beams. The stone cornice which topped the brick parapets leading to the bridge was salvaged then cleaned and restored.

New stones for badly deteriorated sections of the bridge had to be matched and cut to fit. To assist the integration of the modern day stone, one complete corner of the bridge was re-built with new blocks, releasing original material for incorporation in the other corners.

- **Cleaning**
- **Repair**
- **Conservation**
- **Extension**
- **Adaption**
- **Surveys**
- **Budgets**
- **Technical advice**



PAYE

www.payestone.co.uk

Stationmasters House **Mottingham Station Approach** London **SE9 4EL**
Telephone 020 8857 9111 Fax 020 8857 9222
enquiries@payestone.co.uk